User:

Thursday, 28/05/2009 9:11:37 AM

Julie Dawson

Process Sheet

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 48234

Estimate Number P.O. Number

: 12306

This Issue

Written By

: 28/05/2009

Prsht Rev. : NC

First Issue **Previous Run**

: // : 44742

S.O. No. :

: SMALL /MED FAB Type

Part Number

Drawing Name

: D269017

Drawing Number

: D2690 REV. B2

: LANYARD ASSEMBLY

: N/A **Project Number**

: B2 **Drawing Revision**

Material

Due Date

: 04/06/2009

Qty:

& Um:

Each

Checked & Approved By

Comment

: Est:

01.08.24

Removed Manufacturer Release

Certification SM/EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

CBL460

Comment: Qty.:

2.0000 Each(s)/Unit Total:

16.0000 Each(s)

Loop Sleeve

Pick:

Qty 2

Part Number

Description

CBL-460

Loop Sleeve

M11134

2.0

CBL1240

Comment: Qty.:

1.4868 f(s)/Unit

11.8944 f(s) Total:

Cable Pick:

Qty

17"

Part Number CBL-1240

Description Cable

Loop Sleeve

3.0

SMALL FAB 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per Dwg D2690

4.0

QC5

INSPECT WORK TO CURREN

Comment: INSPECT WORK TO CURRENT STEP

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES					
DATE STEP		PROCEDURE CHANGE			By	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Y	'es N	o DQ	A :	Date:	
	Res	solution:	Disposition: Q			QA: N/C Closed: Date:				
NCR:			WORK ORDE	ER NON-CONFORM	ANCE (N	ICR)				
DATE	STEP Description of NC Section A	Description of NC	Corrective Action Section B				Verification		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		gn & late	Section C		Chief Eng	QC Inspector

NOTE: Date & initial all entries

Date:

Thursday, 28/05/2009 9:11:37 AM

Customer: CU-DAR001 Dart Helicopters Services

User:

Julie Dawson

Process Sheet

Drawing Name: LANYARD ASSEMBLY

Job Number: 48234

Part Number: D269017

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE





mF 09.05.29

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
5.475		Description of NC	Corrective Action Section B			Verification				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		

NOTE: Date & initial all entries






		The same of the sa	
DESIGN	DRAWN BY	DART AEROSPACE VICTORIA INTERNATIONAL AIRPORT	
CHECKED	APPROVED B W	DRAWING NO. D2690	REV. B SHEET 1 OF 1
DATE		TITLE	SCALE
97.10.02		LANYARD ASSEMBLY	NTS
Α	97.07.03	NEW ISSUE	



97.10.02 REVISED NOTE FOR ADDITIONAL LENGTH 01.08.20 ADD NOTE TO REMOVE 2.25" OF SLIEDE 31 B2A 04.06.24 ADDED TOLERANCE



D2690-X

X = LENGTH IN INCHES

CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH. NOTE:

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

*ADDITIONAL LENGTH MAY BE NECESSARY IN

SOME APPLICATIONS. CUT AS REQUIRED.

SHOP COPY RETURN TO

FNGINEERING

NOTE:

DEO's

IN SOME CASES, END HAS TO BE CRIMPED UNCONTROLLED COPY ASSEMBLY WITH ATTACHING PARTS

WITHOUT NOTICE WORK ORDER

NO. 4823